## Maryland Historical Trust

Maryland Inventory of Historic Properties number:

Reviewer, NR Program: Peter E. Kurtze

The bridge referenced herein was in									
Historic Bridge Inventory, and SHA									
The Trust accepted the Historic Bri determination of eligibility.	age inventory on April	3, 200	1. In	orias	ge rece	ivea	ne ioi	iowin	g
	MARYLAND HISTOI	RICAI	TRU	ST					
Eligibility RecommendedX		Eligibility Not Recommended							
Criteria:AB <u>&gt;&gt;</u> C	D Considerations:	_A _	B _	_c _	_D_	_E_	F _	G_	_None
Comments:									
Reviewer, OPS: Anne E. Bruder				-	e: 3.		2001		

Date:\_\_3 April 2001\_

MARYLAND INVENTORY OF HISTORIC BRIDGES HISTORIC BRIDGE INVENTORY MARYLAND STATE HIGHWAY ADMINISTRATION/MARYLAND HISTORICAL TRUST

MHT	No.	B-4630

SHA Bridge No. BC 4502 Bridge name Mannasota Avenue over Herring Run
LOCATION: Street/Road name and number [facility carried] Mannasota Avenue
City/town Baltimore Vicinity
County Baltimore
This bridge projects over: Road Railway WaterX Land
Ownership: State County Municipal X Other
HISTORIC STATUS:  Is the bridge located within a designated historic district? Yes NoX  National Register-listed district National Register-determined-eligible district  Locally-designated district Other
Name of district
BRIDGE TYPE: Timber Bridge: Beam Bridge: Truss -Covered Trestle Timber-And-Concrete
Stone Arch Bridge
Metal Truss Bridge
Movable Bridge: Swing Bascule Single Leaf Bascule Multiple Leaf Vertical Lift Retractile Pontoon
Metal Girder:  Rolled Girder:  Rolled Girder Concrete Encased  Plate Girder:  Plate Girder Concrete Encased
Metal Suspension
Metal Arch
Metal Cantilever
Concrete X : Concrete Arch X Concrete Slab Concrete Beam Rigid Frame
Other Type Name

B-4630

DESCRIPTION: Setting: Urban X Small town Rural
Describe Setting:
Bridge BC 4502 carries Mannasota Avenue over Herring Run in the City of Baltimore. Mannasota Avenue extends north-south, while Herring Run flows west to east. The bridge is located within the Herring Run Park, in the eastern portion of the city.
Describe Superstructure and Substructure:
Bridge No. BC 4502 is a 1-span, 2-lane, filled concrete arch bridge. The bridge, built in 1928, is 17 meters (56 feet) long and has a clear roadway width of 9.2 meters (30.1 feet). There are 2 concrete sidewalks on the structure. The east sidewalk is 2 meters (6.7 feet) wide, while the west sidewalk is 2.4 meters (8 feet) wide. The out-to-out width is 14.5 meters (47.5 feet). The superstructure consists of one arch which supports a concrete deck and concrete parapets. The arch spans 15.8 meters (52 feet). The structure has pierced concrete parapets. There are decorative pilasters at the joint between the spandrel walls and wingwalls. A date plaque on the southwest corner of the parapet states that the bridge was built by Harry T. Campbell and Sons. The substructure consists of two concrete abutments and four concrete wingwalls. The bridge has a sufficiency rating of 91.5.
According to the 1995 inspection report, this structure was in satisfactory condition. The parapets on both the east and west sides are heavily deteriorated with spalls and exposed reinforcement bars. The arch has edge spalls and cracks to the arch intrados and one spall with exposed reinforcement bars to the arch headwall. The south abutment has a vertical crack and is severely scaled. The northeast and southeast wingwalls are cracked.
Discuss Major Alterations:
There is no record of major alterations to Bridge BC 4502.
HISTORY:
WHEN was the bridge built: 1928  This date is: Actual X
WHY was the bridge built?
The bridge was constructed in response to the need for more efficient transportation network and increased load capacity.
WHO was the designer?
City of Baltimore

B-4630

TITTO	2012-20	41		0
who	was	tne	DUHA	er.

Harry T. Campbell and Sons

WHY was the bridge altered?

N/A

Was this bridge built as part of an organized bridge-building campaign?

There is no evidence that the bridge was built as part of an organized bridge building campaign.

#### **SURVEYOR/HISTORIAN ANALYSIS:**

This bridge may have National	Register significan	ice for its	association with:
A - Events	B- Person		_
C- Engineering/architec	tural character	X	

The bridge is eligible for the National Register of Historic Places under Criterion C, as a significant example of concrete arch construction. The structure has a high degree of integrity and retains such character-defining elements of the type as pierced concrete parapets, spandrel walls, arch barrel and ring, concrete abutments and wingwalls.

### Was the bridge constructed in response to significant events in Maryland or local history?

The advent of modern concrete technology fostered a renaissance of arch bridge construction in the United States. Reinforced concrete allowed the arch bridge to be constructed with much more ease than ever before and maintained the load-bearing capabilities of the form. As the structural advantages of reinforced concrete became apparent, the heavy, filled barrel of the arch was lightened into ribs. Spandrel walls were opened, to give a lighter appearance and to decrease dead load. This enabled the concrete arch to become flatter and multi-centered, with longer spans possible. Designers were no longer limited to the semicircular or segmental arch form of the stone arch bridge. The versatility of reinforced concrete permitted development of a variety of economical bridges for use on roads crossing small streams and rivers.

Maryland's roads and bridge improvement programs mirrored economic cycles. The first road improvement of the State Roads Commission was a 7 year program, starting with the Commission's establishment in 1908 and ending in 1915. Due to World War I, the period from 1916-1920 was one of relative inactivity; only roads of first priority were built. Truck traffic resulting from war related factories and military installations generated new, heavy traffic unanticipated by the builders of the early road system. From 1920-1929, numerous highway improvements occurred in response to the increase in Maryland motor vehicles from 103,000 in 1920 to 320,000 in 1929, with emphasis on the secondary system of feeder roads which moved traffic from the primary roads built before World War I. After World War I, Maryland's bridge system also was appraised as too narrow and structurally inadequate for the increasing traffic, with plans for an expanded bridge program to be handled by the Bridge Division, set up in 1920. In 1920 under Chapter 508 of the Acts of 1920 the State issued a bond of \$3,000,000.00 for road construction; the primary purpose of these monies was to meet the state obligations involving the construction of rural post roads. The secondary purpose of these monies was to fund (with an equal sum from the counties) the building of lateral roads.

The number of hard surfaced roads on the state system grew from 2000 in 1920 to 3200 in 1930. By 1930, Maryland's primary system had been inadequate to the huge freight trucks and volume of passenger cars in use, with major improvements occurring in the late 1930's.

As the nation's automotive traffic increased in the early twentieth century, local road networks were consolidated, and state highway departments were formed to supervise the construction and improvement of state roads. With a diverse topographical domain encompassing numerous small and large crossings, Maryland engineers quickly recognized the need for expedient design and construction through the standardization of bridge designs.

The concept and practice of standardization was one of the most important developments in engineering of the twentieth century. In Maryland, as in the rest of the nation, the standardized concrete types became the predominant bridge types built. In the period 1911 to 1920 (the decade in which standardized plans were introduced), beams and slabs constituted 65 percent and arches 35 percent of the extant 29 bridges built in Maryland during this period. In the following decade, 1921-1930, the beam (now the T-beam) and slab increased to 73 percent and the arch had declined to 27 percent of the 129 extant bridges; in the next decade (1931-1940), the beam and slab achieved 82 percent and arches had further declined, constituting only 18 percent of the total of extant bridges built on state-owned roads between 1931 and 1946.

Although beam and slab bridges became the utilitarian choice, it appears that the arch was selected when aesthetic as well as other site conditions were considered. The architectural treatment of extant arch bridges supports this assessment. Many of these bridges were multiple span structures with open spandrels or masonry facing. Another decorative feature of the concrete arch bridge was an open, balustrade-style parapet. Despite the popularity of ornamental arches and the increase in use of beam and slab bridges, examples of simpler, single and multiple span closed concrete arch bridges with solid parapets continued to be constructed throughout the early twentieth century.

When the bridge was built and/or given a major alteration, did it have a significant impact on the growth and development of the area?

There is no evidence that the construction of this bridge had a significant impact on the growth and development of this area.

Is the bridge located in an area which may be eligible for historic designation and would the bridge add to or detract from the historic/visual character of the potential district?

Unknown

Is the bridge a significant example of its type?

The bridge is a potentially significant example of a concrete arch bridge, possessing a high degree of integrity.

Does the bridge retain integrity of important elements described in Context Addendum?

The bridge retains the character-defining elements of its type, as defined by the Statewide Historic Bridge Context, including pierced concrete parapets, spandrel walls, arch barrel and ring, concrete abutments and wingwalls, however some deterioration is evident.

B-4630

Is the bridge a significant example of the work of a manufacturer, designer, and/or engineer?

This bridge is a significant example of the work of the City of Baltimore.

Should the bridge be given further study before an evaluation of its significance is made?

No further study of this bridge is required to evaluate its significance.

<b>BIBLIOGRAPHY:</b>
----------------------

City/County inspection/bridge files	X	SHA inspection/bridge files
Other (list):		

Johnson, Arthur Newhall

The Present Condition of Maryland Highways. In Report on the Highways of Maryland. Maryland Geological Survey, The Johns Hopkins University Press, Baltimore.

P.A.C. Spero & Company and Louis Berger & Associates


1995 Historic Highway Bridges in Maryland: 1631-1960: Historic Context Report. Maryland State Highway Administration, Maryland State Department of Transportation, Baltimore, Maryland.

Tyrrell, H. Grattan


1909 Concrete Bridges and Culverts for Both Railroads and Highways. The Myron C. Clark Publishing Company, Chicago and New York.

#### **SURVEYOR:**

Date bridge recorde	d December 1	997
Name of surveyor _	Wallace, Montgomery	& Associates / P.A.C. Spero & Company
		, 40 W. Chesapeake Avenue, Baltimore, MD 21204
Phone number(410)	296-1635	FAX number (410) 296-1670



B-4630 Bridge BC 4502 Mannasota Avenue over Herring Run Baltimore City





Name 4502- MANNASOTA AVE OVER HERRING RYN County/State BALTIMORE CITY/MD
Name of Photographer TIM SCHOEN
Date 1/95
Location of Negative SHR
Description EAST ELEVATION
Number $\frac{\cancel{\cancel{4}} \text{ of } \cancel{\cancel{5}} \cancel{\cancel{5}}}{\cancel{\cancel{5}}}$

Inventory # \_ B - 4636



Name 4502 MANNASOTA AVE OVER HERRING R County/State BALTIMORE CITY/MO	Jur
Name of Photographer TIM SCHOEN	
Date 1/95	
Location of Negative SHA	
Description NORTH APPROACH	
Number 8 of 26 5	

Inventory # <u>B-4630</u>



## Inventory # <u>B-4630</u>

Name 4502 - MANNASOTA AJE OVER HERRING
County/State BALTIM ORE CITY/MD RUN
Name of Photographer TIM SCHOEN
Date1 95
Location of Negative SHA
Description South APPROACH
Number 16 of 36 5

THE RECOMPLETE SECTION OF A RESERVED AS A RE



# Inventory # <u>B-4630</u>

Name 4502-MANNASOTA NE UVER HERRING RUN
County/State BALTIMORE CITY IMD
Name of Photographer TIM SCHUEN
Name of Photographer TIM SCHUEN  Date 195
Location of Negative SHA
Description WEST ELEVATION
1
Number 7 of 36 5
Number 1 of 20

PARTICS BALLSONWOOD REP

TRECTED BY CITY OF BALLIMORE

WM F BROENING MAYOR
C F COOL OTHER EXCHANGES

NATHAN LESMITH, HIGHWAYS ENGINEER

S.M. JOHNSON DESIGNING ENGINEER

HARRY TO CAMPBELL SONS CO. CONTRACTORS

Name 4502-MANUASOTA AVE OVER HERRING RUN County/State BALTIMURE CITY /MO
Name of Photographer TIM SCHOEN
Date 1 95
*
Location of Negative OHR
Description ID PLAQUE @ SOUTH END OF EAS
PARAPET
<i>E</i> -
<b>3</b> ~ 6
Number 8 of 36 5

GENERAL DESCRIPTION OF THE PROPERTY OF THE PRO

Inventory # <u>B-4630</u>